

Set of socket wrenches with CR handle

629CS7CR



Profiles



Product features

Set includes:

• 7x socket wrench with CR handle (article 629CR) dim. 6, 8, 10, 12, 13, 14, 17

| Product name | SKU | Article | Dimensions | Quantity |
|---------------------------------------|--------|----------|--------------------------|----------|
| Set of socket wrenches with CR handle | 617032 | 629CS7CR | 6 - 17 | 7 |
| Socket wrench with CR handle | | 629CR | 6, 8, 10, 12, 13, 14, 17 | 7 |

* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

Safety tips



• Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.

• Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.

• A rounded tip should be redressed with a file; make sure edges are straight.

• Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.

• Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.

• A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes. • Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.

• Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.

• Don't use a screwdriver with a split or broken handle.

• Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

