

# Набор отвёрток, рукоятки NI, в картонной упаковке

607B5NI





## Профили



## Описание товара

### В комплекте:

- 3х отвёртки шлицевых, рукоятка (арт. 605NI) 0.5x3.0x80, 0.8x4.0x100, 1.2x6.5x150
- 2х отвёртки крестовых PH, рукоятка NI (арт. 615NI) PH 1x80, PH 2x100

Наименование товара	SKU	Артикул	Размеры	Количество
Набор отвёрток, рукоятки NI, в картонной упаковке	617037	607B5NI	-	5
Отвёртка шлицевая, рукоятка NI		605NI	0.5 x 3.0x80, 0.8 x 4.0x100, 1.2 x 6.5x150	3
Отвёртка крестовая PH, рукоятка NI		615NI	PH 1x80, PH 2x100	2

\* Изображения продуктов носят демонстрационный характер. Все размеры указаны в миллиметрах, вес в граммах.

## Советы по безопасности



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

### Безопасность (картинки)

