

# Набор отверток, рукоятки ТВИ, в картонной упаковке

600CS5TBI




## Профили





## Описание товара

### В комплекте:

- 1x Отвертка шлицевая, рукоятка ТВИ (арт. 605ТВИ) 0.8x4.0x100
- 2x отвертки шлицевых с шестигранным основанием рабочей части, рукоятка ТВИ (арт. 600ТВИ) 1.0x5.5x100, 1.2x6.5x125
- 2x отвертки крестовых PH с шестигранным основанием рабочей части, рукоятка ТВИ (арт. 616ТВИ) PH 1x80, PH 2x100

Наименование товара	SKU	Артикул	Размеры	Количество
Набор отверток, рукоятки ТВИ, в картонной упаковке	614007	600CS5TBI	-	5
Отвертка шлицевая, рукоятка ТВИ		605TBI	0.8 x 4.0x100	1

Наименование товара	SKU	Артикул	Размеры	Количество
Отвёртка шлицевая с шестигранным основанием рабочей части, рукоятка TBI		600TBI	1.0 x 5.5x100, 1.2 x 6.5x125	2
Отвёртка крестовая PH с шестигранным основанием рабочей части, рукоятка TBI		616TBI	PH 1x80, PH 2x100	2

\* Изображения продуктов носят демонстрационный характер. Все размеры указаны в миллиметрах, вес в граммах.

## Советы по безопасности



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

## Безопасность (картинки)

