

气动角磨刻磨机

1516A



配置文件



产品属性


- 每分钟20000转的空载转速
- 最大气压：6.2 Bar
- 空气消耗量113 升/分钟
- 1/4"进气口
- 夹头能力6 mm
- 内部软管尺寸10mm

优势：

- 此角度设计可研磨普通研磨机无法达到的位置。
- 防止意外启动的安全杆
- 薄切割轮（研磨/抛光针）和其他零件/延伸件的简易夹紧。
- 此尺寸的极限功率
- 小型紧凑工具
- 无级变速调节转速

用途:

- 精确研磨
- 完全研磨
- 工具行业
- 汽车行业
- 航空业
- 焊件清洁
- 混凝土和墙壁表面清洁
- 木材表面清洁
- 清除色彩和光泽
- 除锈
- 轴承研磨
- 发动机阀门研磨
- 齿轮和线圈研磨
- 各种其他表面



	L	A	
617732	162	76	740

* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

用途 (pictures)



Photo (pictures)



Accessories



气动管接头



气动管接头



气动管接头



气动管接头



3/8"气动过滤调节器和润滑器



1/2"气动过滤调节器和润滑器



螺旋气动软管

Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.



- Always disconnect tools not in use from the air supply.

- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.