

Clește combinat pentru electroniști

406/4E




Profile



Caracteristicile produsului

- material: compoziție specială pentru calire revenire
- tratat complet
- părțile tăietoare tratate prin inducție
- manere bimaterial pentru condiții grele



	L	B	C	A	
620069	120	13.6	15.8	8.2	90

capacitatea de taiere (10N=1kg)


	L	
620069	120	max 750 N/mm²Ø1
		1,5

* Imaginea produsului este simbolica.Toate dimensiunile sunt exprimate în mm,greutatea în grame.

0 (pictures)



Photo (pictures)





Safety tips



- Pliers should be oiled regularly. A drop of oil at the hinge will lengthen the tool life and assure easy operation.
- When cutting wire with pliers, you should always wear glasses or goggles.
- Handles are provided for comfort. They are not intended to give user any degree of protection against electric shocks and should never be used on live electric circuits.



- Don't use pliers for cutting hardened wire, unless specifically manufactured for this purpose.
- Don't expose pliers to excessive heat. This may ruin the tool.
- Don't use pliers as a hammer.
- Don't hammer on the handles. They may crack or break.
- Don't extend the length of plier handles to secure greater leverage.
- Don't use pliers on nuts or bolts. A wrench will do a better job and with less risk of damage to the fastener.