

Garnitura udarnog pneumatskog čekića sa sjekačima

1514PB










Profili

 1 year

Atributi proizvoda

- dimenzije kutije: 307x260x70 mm

Naziv proizvoda	SKU	Članak	Standardi	Količina
Garnitura udarnog pneumatskog čekića sa sjekačima	619964	1514PB	-	7
Čekić pneumatski		1514	170	1
Sjekač plosnati		1514A1	182	1
Špica		1514A2	180	1
Sjekač za varove		1514A3	180	1
Sjekač za lim s rascjepom		1514A4	180	1
Sjekač za lim s rascjepom		1514A5	190	1
Sjekač široki		1514A6	178	1
Plastična kutija za nasadne ključeve		981PBM2	307x260x74	1

* Slike proizvoda su simbolične. Sve dimenzije su u mm, masa je u g.

Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.